

#### Airworthiness Committee Status Report

New Board Meeting 9 September 2010 Annual Convention San Diego, CA



#### Focus on Parts Availability

- Needs include:
  - Structural metal parts
  - Formed metal parts
  - Forged and machined parts
- Parts not deemed difficult to obtain
  - Engine parts
  - Propeller parts
  - Wheels and calipers
  - Service limited parts (tires, plugs, filters, etc.)
  - Mechanical hardware



### **Structural Metal Parts**

- Reports of cracked rudder spars
  - Easily formed by competent shop
  - Simple bends on a brake
  - Match drill at replacement



## **Formed Metal Parts**

- Gear Up/Collapse Landing
  - Requires replacement of frames, longerons and skins
  - Formed on tooling using 2024-0 condition material
  - After forming, heat treat to T42 condition
  - Install using conventional riveting methods
- Two Shops Known to have Tooling
  - Webco
  - Aircraftsman
- Parts are fabricated as "Owner Produced" per 21.303



## Forged and Machined Parts

- This may become a problem in the Future
  - Piper is producing torque tubes and horns
  - Australians are in process of producing horns
- New Production Parts
  - Requires an STC and PMA to be fabricated and sold
  - If owner produced, still requires design approval



## Webco Parts Supply





# Webco Parts Supply





## Webco Repairs

- Has DER approval to overhaul fuel valves for Twins
  - Unknown if valves for singles are included
  - New valves in production
- Landing gear motors and transmissions not serviced
  There may be other providers
- Fuel boost pumps not serviced
  - There are other provides of new and overhaul units
- Existing PMA'd parts approval still valid and producible
- Bob Weber has indicated to Dave F that historical knowledge will be passed to ICS if things go bad



## Summary

- At the present time, parts availability is not deemed critical
- As Fleet ages, some parts may become rare
- "Owner Produced" parts allows considerable flexibility
- Work must continue to locate all serviceable and new parts